




## 3 PHASEMOTORS


# KE31 32M2-4

### CONNECTION DIAGRAM AND PROTECTION - RMS SERIES


Connection Diagrams (Three Phase Motors with Cage Rotor)



Delta Connection




Star Connection




Connection to Star-Delta Starter

Multi-speed motors in Dahlander connection  
(Tapped winding)




Low Speed




High Speed

Multi-speed motors with 2 separate windings



Low Speed



High Speed

All motors comply to the international standard IEC60034-5. This standard specifies the Degree of Protection of each electric equipment, commonly known as the "IP" code. See table below

### CONNECTION DIAGRAM

